

NOTICE D'UTILISATION

Fonctions

Pile : 1 x 1.5V (LR44)

Date/heure/alarme

Horloge avec sonnerie et fonction alarme

Plage de température : -10+70°C ou +14+158°F


Plage hygrométrie : 10 à 90 %

Résolution : 0,1°C, 1 %

Précision : +/-1°C, +/-5 %

Enregistrement des températures mini et maxi

Thermomètre




1. Ecran
2. Heure
3. Température
4. Zone de confort
5. Boutons
6. Support
7. Humidité
8. Trou de suspension
9. Couvercle pile

Boutons

« MODE » : changement du mode heure et alarme, appuyer sur le bouton plus longtemps pour programmer l'heure et l'alarme
 « ADJ » : pour changer l'unité, lors de la programmation de l'heure, la date et l'alarme. Maintenir appuyé pour accélérer.
 « MIN/MAX » : affiche les températures et l'humidité max et min. Rester appuyé plus longtemps pour remettre à zéro la mémoire
 °C/°F : pour changer l'unité de mesure

Mise en marche

Installer la pile




Heure : AM 12:00
 Date : 1 M 1 D
 Alarme : AM 12:00, alarme OFF
 Température et humidité actuelle


Référence produit :6030
 Type de batterie: 1X1.5V 160mAh LR44 Alkaline Cell
 Adresse du fabricant de pile:
 SHENZHEN WEINENG ELECTRONICS CO.,LTD
 7th floor of A-building, Senyang High-tech Park,
 Tianliao community, Guangming District,
 Shenzhen.China
 Site web : www.weineng-gd.com
 Email:weinengdz@163.com




Programmation date et heure



Programmation alarme



Activation Alarme/sonnerie par heure



Le son de l'alarme sonne bi bi bi pendant 1 min. La sonnerie horaire sonne bi-bi une fois

Température max/min et humidité : enregistrement et remise à zéro

Appuyer sur max/min pour avoir les minima et maxima de température et humidité. Appuyer 3 secondes pour remettre à 0.

Zone de confort


Température : entre 20 et 26°C (68 et 78°F) / humidité : entre 50 et 70% (humide >70 %, sec <50%). Inconfort température : <20°C (68°F) ou >26°C (78°F)

USER MANUAL

Functions

- Battery: 1.5 Vx1 (LR44)
- Time/date/alarm
- Clock with hourly chime and alarm function
- Temperature range: -10+70°C or +14+158°F
- Humidity range: 10-90%
- Resolution: 0,1°C, 1%
- Accuracy: +/-1°C, +/-5%
- Max/Min temperature and humidity records

Thermometer



- LCD
- Time
- Temperature
- Comfortable level
- Buttons
- Support
- Humidity
- Hanger
- Battery cover

Buttons:

- MODE:** to switch time and alarm mode, hold the button to set time and alarm
- ADJ:** to switch time and date mode, in setting mode press and hold the button to increase the value
- MAX/MIN:** display the max and min temperature and humidity value. Hold for a long time to reset the memory
- °C/°F:** to switch the unit of temperature between °C/°F

Use

Open the battery cover; insert the battery, the LCD displays




Time: AM 12:00
Date : 1 M 1 D
Alarm : AM 12:00, alarm OFF
The current temperature and humidity


Product reference: 6030
Bettry type: 1X1.5V 160mAh LR44 Alkaline Cell
Battery Manufacturer Address:
SHENZHEN WEINENG ELECTRONICS CO.,LTD
7th floor of A-building, Senyang High-tech Park,
Tianliao community, Guangming District,
Shenzhen.China
Website: www.weineng-gd.com
Email:weinengdz@163.com




Programmation date et heure



Alarm set



Alarm on/off, hourly chime set



Alarm sound: bi bi bi bi for 1 minute
Hourly chime sound: bi bi for 1 time

Maximum and minimum temperature and humidity record and clear

Press MAX/MIN button to have the min and max temperature and humidity. Press 3 seconds to clear

Comfort level

Temperature: between 20 and 26°C (68 and 78°F) / humidity: between 50 and 70% (wet >70%, dry <50%)

No comfort: <20°C (68°F) or >26°C (78°F)